

Desanding / Mat Shaker / Mat Beater	Removing dirt and debris prior to washing can be beneficial to the wash process. The dry solid matter is also more easily disposed of.
Washer Extractor	Do not use dry cleaning machines, dishwashers or ozonated water systems
Partition - Y or Open Pocket	
Centrifuge - G force	G Force more than 600 is not allowed
Rotations per minute - RPM	
Tunnel Washer	Do not use dry cleaning machines, dishwashers or ozonated water systems
Centrifuge - G force	G Force more than 600 is not allowed
Rotations per minute - RPM	
Membrane Press	
Press pressure - bar	
Tamping Process employed or not	
	Do not over dry mate. As a constal quideling, maisture weight should be 10.% to 15.% of
Tumble Dryer	Do not over dry mats. As a general guideline, moisture weight should be 10 $\%$ to 15 $\%$ of the fabric weight
<b>Tumble Dryer</b> Gas or steam	
Gas or steam	
Gas or steam Infrared controlled	
Gas or steam Infrared controlled Inlet temperature	
Gas or steam Infrared controlled Inlet temperature Drum temperature	the fabric weight
Gas or steam Infrared controlled Inlet temperature Drum temperature Mat temperature	the fabric weight
Gas or steam Infrared controlled Inlet temperature Drum temperature Mat temperature Drying Time	the fabric weight
Gas or steam Infrared controlled Inlet temperature Drum temperature Mat temperature Drying Time	the fabric weight
Gas or steam Infrared controlled Inlet temperature Drum temperature Mat temperature Drying Time Cool Down Process ?	the fabric weight   Recommended between 60 °C and 80° C   Mats should be removed from the dryer promptly upon completion of the drying cycle
Gas or steam Infrared controlled Inlet temperature Drum temperature Mat temperature Drying Time Cool Down Process ?	the fabric weight   Recommended between 60 °C and 80° C   Mats should be removed from the dryer promptly upon completion of the drying cycle
Gas or steam Infrared controlled Inlet temperature Drum temperature Mat temperature Drying Time Cool Down Process ? Storage Conditions	the fabric weight   Recommended between 60 °C and 80° C   Mats should be removed from the dryer promptly upon completion of the drying cycle