

Below is Kleen-Tex's recommend storage guidelines. Your mat's warranty may be affected if the following guidelines are not adhered to.



Mats must be stored flat when being stored for more than 4 weeks



Mats must be covered and kept out of direct sunlight whilst being stored



Maximum ozone level must not exceed 120 $\mu\text{g}/\text{m}^3$



Minimum storage temperature must not exceed -20C



Maximum storage temperature must not exceed $+40\text{C}$



Humidity level – relative humidity maximum 65 %